



1 Viton TU2K Ball Check Valve Repair Kit

RGCK2VRK010



Details

Repair kits for True Union 2000 Single Entry Ball Check Valves.

Specifications

Manufacturer	Spars
Fitting Size	1
Seal Type	Viton

Pekerti Jaya Sdn. Bad

45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600
603-80216684

<https://pekertijaya.rrproducts.com/>