



3 Viton TU2K Ind Ball Check Valvee Repair Kit RGCK2VRK030



Details

Repair kits for True Union 2000 Single Entryl Ball Check Valves.

Specifications

Manufacturer	Sparks
Fitting Size	3
Seal Type	Viton

Pekerti Jaya Sdn. Bad

45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600
603-80216684

<https://pekertijaya.rrproducts.com/>