



NGK Spark Plug - TR55GP

RN3403



Replaces

Autolite	AP5184, AP5243, AP5245, AP605, AP606
Bosch	HR8DPP30V, HR8DPP30Y
Champion	3015, 3015-2, 3401, 3401-2, 3408, 3983, 3983-2, 7015, 7940

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Pekerti Jaya Sdn. Bad

45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600
603-80216684

<https://pekertijaya.rrproducts.com/>