



## NGK Spark Plug - TR55 RN3951



### Replaces

|            |                                                                                                                          |
|------------|--------------------------------------------------------------------------------------------------------------------------|
| AC Delco   | 41-600, 41-601, 41-606,<br>5614283, 5614284,<br>92141875, R42LTS6,<br>R43LTS6, R43LTSX,<br>R44LTS6, R44LTSM6,<br>R45LTS6 |
| Autolite   | 603, 604, 605, 884                                                                                                       |
| Bosch      | H7DCY, HR9DCY                                                                                                            |
| Champion   | 13C2, 13S, 4013, 4983,<br>RS12YC6, RS14YC6                                                                               |
| Denso      | T16EPR-U15, T20EPR-<br>U15                                                                                               |
| MotorCraft | AGRF22-6, AGRF32-6,<br>AGSF23C, AGSF42C-6,<br>AWRF32-5                                                                   |

### Specifications

|                  |     |
|------------------|-----|
| Manufacturer     | NGK |
| Box Quantity     | 4   |
| Package Quantity | 1   |

**Pekerti Jaya Sdn. Bad**

45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600  
603-80216684

<https://pekertijaya.rrproducts.com/>