




# Kohler Gasket, Exhaust Manifold

RK2504117S



## Replaces

Kohler

24 041 02-S, 24 041 49-S, 25 041 17-S

## Specifications

Manufacturer

Kohler

**Pekerti Jaya Sdn. Bad**

45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600  
603-80216684

<https://pekertijaya.rrproducts.com/>