

## **Coupling - Compression w/Floloc 3/4** RG11207





## **Details**

As cap is tightened, pressure causes the gripping ring to bite into the pipe eliminating pull out.

## **Specifications**

Manufacturer Manufacturer's Model No

Flo Control 112-07

**Pekerti Jaya Sdn. Bad**45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600
603-80216684