

Coupling - Compression w/Floloc 1 RG11210





Details

As cap is tightened, pressure causes the gripping ring to bite into the pipe eliminating pull out.

Specifications

Manufacturer Manufacturer's Model No

Flo Control 112-10

Pekerti Jaya Sdn. Bad 45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600 603-80216684 https://pekertijaya.rrproducts.com/