



1-1/4,1-1/2 Viton Gate Valve Repair Kiti

RGGTVRK015



Details

1/2" - 2" Kit includes: 1-Stem O-ring, 1-Bonnet O-Ring, 1-Stem Bushing, 1-Stem Washer. 2-1/2" - 3" Kit includes: 1-Stem O-ring, 1-Seal Carrier O-ring, 1-Stem Bushing, 1-Stem Washer 4" Kit includes: 1-Stem O-ring, 1-Bonnet O-ring, 1-Stem Bushing,

Specifications

Manufacturer	Spars
Manufacturer's	GT-VRK-015
Model No	
Seal Type	Viton

Pekerti Jaya Sdn. Bad

45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600
603-80216684

<https://pekertijaya.rrproducts.com/>