



1/2 Vtn TU2K Std Ball Valve Repair

RGTU1VRK005



Details

Standard Kit includes: 2-HDPE/PTFE Seats 2-End Connector O-rings 2-Stem O-rings 1-Seal Carrier O-ring 2-Seat O-rings (where applicable)

Specifications

Manufacturer	Spars
Fitting Size	1/2
Seal Type	Viton

Pekerti Jaya Sdn. Bad

45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600
603-80216684

<https://pekertijaya.rrproducts.com/>