



NGK Spark Plug - BKR5ES-11

RN2382



Replaces

Autolite	3926
----------	------

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Pekerti Jaya Sdn. Bad

45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600
603-80216684

<https://pekertijaya.rrproducts.com/>