



NGK Spark Plug - GR45GP

RN3142



Replaces

Autolite	AP646
Champion	3031, 3031-2

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Pekerti Jaya Sdn. Bad

45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600
603-80216684

<https://pekertijaya.rrproducts.com/>