



NGK Spark Plug - TR5GP RN3186



Replaces

Autolite	AP104, AP105, AP106, AP5164
Bosch	HR8DPP30X, HR8LPP30U
Champion	3013, 3013-2, 3407, 7963, 7983
Denso	PT16TT

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Pekerti Jaya Sdn. Bad

45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600
603-80216684

<https://pekertijaya.rrproducts.com/>