



# NGK Spark Plug - BR7HS

RN4122



## Details

Replaces Champion RL82C

## Replaces

|            |                                                                        |
|------------|------------------------------------------------------------------------|
| AC Delco   | R41CF, S42FR*                                                          |
| Autolite   | 3684                                                                   |
| Bosch      | WR5A, WR5AC                                                            |
| Champion   | 874, 874-1, 874C,<br>874M, 874S, RL4J,<br>RL77J, RL78, RL78C,<br>RL82C |
| Denso      | TR22, W22FSR,<br>W22FSR-U                                              |
| MotorCraft | AER2X                                                                  |

## Specifications

|                  |       |
|------------------|-------|
| Manufacturer     | NGK   |
| Manufacturer's   | BR7HS |
| Model No         |       |
| Box Quantity     | 10    |
| Package Quantity | 1     |

**Pekerti Jaya Sdn. Bad**

45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600  
603-80216684

<https://pekertijaya.rrproducts.com/>