



NGK Spark Plug - FR5AP-10 RN6371



Replaces

Champion	3340, 3340-2
Denso	K16PR-P11

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Pekerti Jaya Sdn. Bad

45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600
603-80216684

<https://pekertijaya.rrproducts.com/>