


Replaces Toro Groundsmaster 4500-D Parts



Traction Unit with Yanmar Engine - Model 30881A Rear Lift Arm Hydraulics





Replaces Toro Groundsmaster 4500-D Parts



Traction Unit with Yanmar Engine - Model 30881A Rear Lift Arm Hydraulics

	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
Hose	s				
10	R105-9238	105-9238	Hydraulic Hose Assy	4	
13	R104-5505	104-5505	Hydraulic Hose Assy	4	
17	R104-5502	104-5502	Hydraulic Hose Assy	2	
Othe	r Parts Avail	able			
11	R340-70	340-70	Nut - Lock	2	
12	R340-74	340-74	Locknut - Bulkhead	4	
14	R117-5141	105-9820, 105-9872, 117-5141, 137-5571	Hydraulic Motor	2	
15	R237-80	237-80, 327-80	O-Ring	4	
16	R340-17	340-17	No 10 Male Orfs x No 10 Male Orb	4	
18	R237-65	237-65, 237.65	O-Ring	4	
19	R237-21	237-21, 327-21	O-Ring	2	
20	R340-92	340-92	Hydraulic Fitting - Striaght	2	
21	R237-22	107-8844, 237-22, 237-78	O-Ring	2	