



Kohler Electric Starter-Bendix Drive

RK2509807S



Replaces

Kohler

25 098 03-S, 25 098 04-S, 25 098 05-S, 25 098 06-S, 25 098 07, 25 098 07-S

Specifications

Manufacturer

Kohler

Pekerti Jaya Sdn. Bad

45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600
603-80216684

<https://pekertijaya.rrproducts.com/>