


Replaces Exmark Lazer Z HP-Series Parts



Zero-Turn Mower with 50 in Deck - Models LHP23KA505, LHP27KC505, LHP27KC505R 50in Deck





Replaces Exmark Lazer Z HP-Series Parts



Zero-Turn Mower with 50 in Deck - Models LHP23KA505, LHP27KC505, LHP27KC505R 50in Deck

	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
40	R103-8415	103-8415	Roller - Anti Scalp	6	
51	R323-11	323-11	Bolt - 3/8-16 x 2 1/4 GR5	2	
52	R98-5975	98-5975	Washer - Belleville	5	
53	R1-613098	1-613098	Pulley- Idler	1	
54	R104-8301	104-8301, 109-6658	Locknut - 3/8-16 Nylon Flanged	3	
55	R1-633456	1-633456	Bushing - Idler	3	
56	R453011	3256-23, 3256-24, 3256-3, 3256-4, 80-7730	Washer - Flat 3/8 SAE Y/Zinc	12	
57	R1-633029	1-633029	Ball Joint - 5/8-18 RH Thread	2	
58	R3219-6	3219-6	Nut - 5/8-18 Gr 8 Hex	2	
59	R3256-27	3256-27	Washer - Flat 5/8 SAE	2	
60	R3217-11	3217-11	Nut - Hex 5/8-11	10	
63	R32128-43	32128-43, 3290-357, 3296-29	Nut - Flanged Whiz - 3/8-16	3	
64	R322-3	322-2, 322-3	Bolt - Hex HD 5/16-18 x 3/4	2	
65	RF104	3253-8	Washer - Lock 5/8	2	
66	R1-632199-01	1-632199-01	Pin - Strut	2	
67	R103-3037	103-3037	Splined Bushing	3	
68	R1-633447	1-633447	Chain - Deck Lift	4	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Exmark Lazer Z HP-Series Parts



Zero-Turn Mower with 50 in Deck - Models LHP23KA505, LHP27KC505, LHP27KC505R 50in Deck

Item R&R No Part No.	OEM Part No.	Description	Qty Order Req Quantity
72 R103-9539	103-9539	Spindle Housing Assy with Bearings	3
75 R109-2102	109-2102	Spindle Housing Assy with Bearings and Shaft	3
77 R3296-39	32128-43, 3296-39	Locknut - 3/8-16 Nylon	18
78 R32128-37	32128-37	Nut - 7-16-14 Hx Serr Fl	16