



# 1-1/2 Viton TU2K Ball Check Valve Repair Kit RGCK2VRK015



## Details

Repair kits for True Union 2000 Single Entryl Ball Check Valves.

## Specifications

Manufacturer	Spars
Fitting Size	1-1/2
Seal Type	Viton

## Pekerti Jaya Sdn. Bad

45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600  
603-80216684

<https://pekertijaya.rrproducts.com/>