



1/2,3/4 & 1 Viton Gate Valve Repair

RGPGTVRK010



Details

Plug Gate Valve O-ring 1/2" - 2" Repair Kits include:
1-Stem O-ring 1-Bonnet O-Ring

Specifications

Manufacturer	Spars
Seal Type	Viton

Pekerti Jaya Sdn. Bad

45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600
603-80216684

<https://pekertijaya.rrproducts.com/>