



# 3/4 Vtn TU2K Std Ball Valve Repair

RGTU1VRK007



## Details

Standard Kit includes: 2-HDPE/PTFE Seats 2-End Connector O-rings 2-Stem O-rings 1-Seal Carrier O-ring 2-Seat O-rings (where applicable)

## Specifications

Manufacturer	Spars
Manufacturer's	TU1-VRK-007
Model No	
Seal Type	Viton

## Pekerti Jaya Sdn. Bad

45 Jalan Industri USJ 1/5, Taman Perindustrian USJ 1 Subang Jay, 47600  
603-80216684

<https://pekertijaya.rrproducts.com/>